


Grave Creek Watershed Water Quality and Habitat Restoration Plan and Sediment Total Maximum Daily Loads



March 2005

Significant Contributors

DEQ
Kootenai River Network
River Design Group, Inc.

TABLE OF CONTENTS

[SECTION 1.0 INTRODUCTION](#)

[SECTION 2.0 WATERSHED CHARACTERIZATION](#)

[SECTION 3.0 REGULATORY FRAMEWORK AND TMDL DEVELOPMENT](#)

[SECTION 4.0 STREAM CONDITION DATA SUMMARIES](#)

[SECTION 5.0 REFERENCE CONDITIONS AND WATER QUALITY IMPAIRMENT STATUS UPDATES FOR THE GRAVE CREEK PLANNING AREA](#)

[SECTION 6.0 SEDIMENT LOADING SOURCE ASSESSMENT SUMMARY](#)

[SECTION 7.0 RESTORATION OBJECTIVES](#)

[SECTION 8.0 WATER QUALITY AND HABITAT RESTORATION PLAN IMPLEMENTATION STRATEGY](#)

[SECTION 9.0 WATER QUALITY AND FISH HABITAT MONITORING PLAN](#)

[SECTION 10.0 PUBLIC AND STAKEHOLDER INVOLVEMENT](#)

[SECTION 11.0 REFERENCES SITED](#)

LIST OF APPENDICES

[APPENDIX A: HARVEST ANALYSIS SUMMARY](#)

[APPENDIX B: ROADS ANALYSIS SUMMARY](#)

[APPENDIX C: RAIN-ON-SNOW, WATER YIELD, EQUIVALENT CLEARCUT ACREAGE AND PEAK FLOW INCREASES ANALYSIS SUMMARY](#)

[APPENDIX D: FISHERIES AND AQUATIC LIFE](#)

[APPENDIX E: REGULATORY FRAMEWORK AND TMDL DEVELOPMENT](#)

[APPENDIX F: SUMMARY OF DATA COLLECTION AND ASSESSMENT METHODOLOGIES](#)

[APPENDIX G: STREAM CONDITIONS](#)

[APPENDIX H: REFERENCE VALUE DEVELOPMENT FOR THE GRAVE CREEK WATERSHED](#)

[APPENDIX I: ROAD SURFACE SEDIMENT ANALYSIS METHODS AND RESULTS](#)

[APPENDIX J: IN-STREAM SEDIMENT SOURCE ANALYSIS](#)

[APPENDIX K: RESPONSE TO COMMENTS](#)

LIST OF PHOTOS

[PHOTO 1: CLARENCE CREEK – RIPARIAN HARVEST](#)

[PHOTO 2: STAHL CREEK – RIPARIAN HARVEST WITH NO BUFFER](#)

[PHOTO 3: MAIN STEM MIDDLE – CUT LOGS IN-STREAM – MARGINAL HABITAT](#)

[PHOTO 4: MAIN STEM UPPER – TYPICAL AVALANCHE CHUTE](#)

[PHOTO 5: LEWIS – TYPICAL NATURAL AVALANCHE CHUTE](#)

[PHOTO 6: MAIN STEM UPPER – ROAD FILL ROAD ENCROACHMENT](#)

[PHOTO 7: MAIN STEM UPPER – BANK EROSION](#)

[PHOTO 8: STAHL CREEK – RIPARIAN HARVEST WITH NO BUFFER AND WITH MASS WASTING](#)

[PHOTO 9: BLUE SKY – RIPARIAN MODIFICATION AND MASS WASTING](#)

[PHOTO 10: WILLIAMS – ROAD ENCROACHMENT AND RIPARIAN HARVEST WITH MASS WASTING](#)

[PHOTO 11: MAIN STEM UPPER – EXAMPLE OF IN-STREAM LWD REMOVAL](#)

[PHOTO 12: MAIN STEM LOWER BELOW CANYON – BANK EROSION AND EVIDENCE OF AGGRADATION](#)
[PHOTO 13: MAIN STEM LOWER ABOVE CANYON – EVIDENCE OF AGGRADATION](#)
[PHOTO 14: MAIN STEM UPPER – TYPICAL REACH CONDITION](#)
[PHOTO 15: MAIN STEM UPPER – MID-CHANNEL BAR, EVIDENCE OF POSSIBLE AGGRADATION](#)
[PHOTO 16: MAIN STEM UPPER – CHECK DAM](#)
[PHOTO 17: MAIN STEM UPPER – GABION FOR FILL SLOPE PROTECTION](#)
[PHOTO 18: MAIN STEM UPPER – AVALANCHE SLIDE – WOODY DEBRIS CONTRIBUTION](#)
[PHOTO 19: MAIN STEM LOWER BELOW CANYON – TERRACE EROSION](#)
[PHOTO 20: MAIN STEM LOWER – BANK ARMORING](#)
[PHOTO 21: FISH PASSAGE BARRIER ON FOUNDATION CREEK](#)

LIST OF MAPS

[MAP 1: VICINITY MAP](#)
[MAP 2: LAND OWNERSHIP](#)
[MAP 3: 2000 CENSUS POPULATION DENSITY](#)
[MAP 4: TOPOGRAPHY](#)
[MAP 5: LANDTYPES](#)
[MAP 6: HYDROGRAPHY](#)
[MAP 7: IRRIGATION DIVERSIONS](#)
[MAP 8: VEGETATION LAND COVER](#)
[MAP 9: FOREST MANAGEMENT ACTIVITIES: NUMBER OF HARVEST ENTRIES](#)
[MAP 10: ROAD SYSTEM](#)
[MAP 11: RAIN ON SNOW ZONE](#)
[MAP 12: FISH DISTRIBUTION](#)
[MAP 13: SURVEYED R1/R4 REACHES AND ROSGEN STREAM TYPES](#)
[MAP 14: IN-STREAM SEDIMENT SOURCES](#)
[MAP 15: SEDIMENT SOURCES IDENTIFIED FROM AIR PHOTO INTERPRETATION](#)